

2022 Ascent

1. Customer states at slow speeds, hears a creaking sound on passenger side. Tech found kitchen cabinet coming loose from the wall. Test drove to confirm issue. He removed upper drawer in cabinet and added screws to cabinet/ re-drove unit and creaking gone. 1.0 **1.0 approved.**