## **APPLICABLE VEHICLES**

2020-2023 Tacoma

### **CONDITION**

Some 2020-2023 Manual Transmission Tacoma vehicles may exhibit an abnormal clutch pedal creak/squeak sound during operation.

Clutch pedal Creak/Squeak Example



### **RECOMMENDATIONS**

This issue in being investigated. Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

# Prior to contacting TAS, confirm/attach the following to the case:

- 1. Video of the sound duplicating
- 2. No previous repairs/lubrication of related clutch pedal parts
- 3. No separation of any clutch pedal parts has occurred
- 4. Temperature and humidity conditions during duplication

### **LINK REFERENCES**

This Tech Tip does not contain any link references