


1. Gap in fork
2. Full wear on rotor

Figure 1. Correct Fork Lower



1. Gap in fork
2. Outer wear on rotor

Figure 2. Incorrect Fork Lower

## Credit Procedure

### NOTE

Enter M1584 into the Event Comments of the claim.

**The failed part and replacement part will be the same in this instance.**

Submit a warranty claim in the United States per Table 5 and China per Table 6.

Table 5. Credit Procedure for Dealers in the United States

ITEM	DATA
Claim Type	PRD or MC
Problem Part Number	HD43200P1000A5
Quantity	1
Primary Labor Code	2346
Labor Time	0.6 hours
Customer Concern Code	9203
Condition Code	9102

Table 6. Credit Procedure for Dealers in the China

ITEM	DATA
Claim Type	PDI Claim or Standard Claim
Problem Part Number	HD43200P100006
Quantity	1
Primary Labor Code	2346
Labor Time	0.6 hours
Customer Concern Code	9203
Condition Code	9102