

SSM 51575

2020-2022 Escape (CX482N) (TC)

2020-2022 Escape - Low Beams Turn On By Themselves When Vehicle Is Off For 10 Minutes Or More - DTC B1533

Some 2020-2022 Escape vehicles may exhibit a condition where the low beams turn on by themselves when vehicle is OFF for 10 minutes or more with diagnostic trouble code (DTC) B1533 stored in the body control module (BCM). This may be due to the internal logic within the headlamp switch. To correct this condition, replace the headlamp switch (service base PN: 11654). Refer Workshop Manual, Section 417-01.