

## **Technical Service Bulletin**

Technical Service Bulletin: TSB220227 Released Date: 24-Apr-2023

New Installation Procedure for Tappet Guide Screws to Reduce Lubricating Oil Leaks

# New Installation Procedure for Tappet Guide Screws to Reduce Lubricating Oil Leaks

## Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

#### **Product Affected**

- ISC CM850
- ISC8.3 CM2250
- ISL CM2150
- ISL CM850
- ISL8.9 CM2150 L110
- ISL9 CM2150 SN
- ISL9 CM2250
- ISL9 CM2350 L101
- ISL9 CM2350 L111
- ISLE4 CM850
- L8.9 L121
- L9 CM2350 L116B
- L9 CM2350 L119B
- L9 CM2350 L120C
- L9 CM2450 L126B
- L9 CM2670 L128B
- QSC8.3 CM850
- QSC8.3 CM850(CM2850)

- QSL9 CM2250
- QSL9 CM2350 L102
- QSL9 CM2350 L118
- QSL9 CM850
- QSL9 CM850(CM2850)
- QSL9 M CM2250 L106

#### Issue

#### Symptom:

 External lubricating oil leaks can occur at the tappet guide screw. Lubricating oil will be visibly leaking from the tappet guide screw down the exterior of the cylinder block.

#### **Root Cause:**

 The service manual literature contained incorrect tappet guide screw installation instructions.

#### Verification

To confirm the lubricating oil leak location, see the corresponding Service Manual. Reference Procedure 014-024 in Section 14.

#### Resolution

The tappet guide screw installation procedure has been updated. See corresponding Service Manual. Reference the Clean and Inspect for Reuse step of Procedure 004-015 in Section 4. See Table 2 below. The tappet guide screw can be removed and reused without removal of the tappet.

#### **Reason for Change**

The thread locker amount and torque specification in Procedure 004-015 in Section 4 were found insufficient, which can result in external lubricating oil leaks.

#### **Production Status**

Implemented for production. See Table 1.

Table 1, Production Information					
ESN First	Build Date <sup>1</sup>	Plant			
9947759	24 August 2022	Rocky Mount Engine Plant			
<sup>1</sup> Engine build date can be found on engine dataplate.					
	·	·			

#### **Publications Affected**

Table 2, Publications Affected  Manual Bulletin Procedure					
туре	Engine	Number	Title	Procedure	Section
Service Manual	ISC CM850	4021418	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr.html)	4
Service Manual	ISC8.3 CM2250	4022257	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr- iscl10.html)	4
Service Manual	ISL CM850	4021418	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr.html)	4
Service Manual	ISL CM2150	4021569	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr- iscl07.html)	4

Table 2, Pu	Table 2, Publications Affected				
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	ISL/NS6 2670	4021418	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr.html)	4
Service Manual	ISL8.9 CM2150 L110	4358475	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/3 23/323- 004-015- tr.html)	4
Service Manual	ISL9 CM2150 SN	4022190	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr- isle5.html)	4
Service Manual	ISL9 CM2250	4022257	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr- iscl10.html)	4

Table 2, Pu	Table 2, Publications Affected				
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	ISL9 CM2350 L101	4310787	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/1 85/185- 004-015- tr.html)	4
Service Manual	ISL9 CM2350 L111	4367223	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/3 41/341- 004-015- tr.html)	4
Service Manual	ISLE4 CM850	4021418	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr.html)	4
Service Manual	L8.9 L121	5411055	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 47/447- 004- 015.html)	4

Table 2, Pub	Table 2, Publications Affected				
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	L9 CM2350 L116B	5411330	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 59/459- 004- 015.html)	4
Service Manual	L9 CM2350 L119B	5411456	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 59/459- 004- 015.html)	4
Service Manual	L9 CM2350 L120C	5504199	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/5 60/560- 004- 015.html)	4

Table 2, Publications Affected					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	L9 CM2450 L126B	5613077	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/5 83/583- 004- 015.html)	4
Service Manual	QSC8.3 CM850	4021418	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr.html)	4
Service Manual	QSC8.3 CM850 (CM2850)	4021418	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr.html)	4
Service Manual	QSL	4022256	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr- qslt4i.html)	4

Manual _ Bulletin Procedure					
Туре	Engine	Number	Title	Procedure	Section
Service Manual	QSL9 CM850	4021418	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr.html)	4
Service Manual	QSL9 CM850 (CM2850)	4021418	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr.html)	4
Service Manual	QSL9 CM2250	4022256	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr- qslt4i.html)	4
Service Manual	QSL9 CM2350 L102	4332796	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/2 61/261- 004-015- tr.html)	4

Table 2, Pub	Table 2, Publications Affected				
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	QSL9 CM2350 L118	4388673	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 21/421- 004- 015.html)	4
Service Manual	QSL9 M CM2250 L106	4022256	Tappet	Refer to Procedure 004-015 (/qs3/pubsy s2/xml/en/p rocedures/4 5/45-004- 015-tr- qslt4i.html)	4

## **Document History**

Date	Details
2022-11-8	Module Created
2023-4-20	Updated Resolution section.

Last Modified: 24-Apr-2023