Subject: Engineering Information - Front Bumper Fascia Skid Plate Loose, Disengaged and/or Falling Off

This PI has been revised to end the need for gathering information from the field. Please discard PIE0723.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Cadillac	XT5	2021	2023	_	_	_	_

If you encounter a vehicle with the above condition, refer to Bulletin 23-NA-028 in SI for further diagnosis.

Version	2
Modified	Released October 20, 2022 Revised April 03, 2023 - Ended the need for gathering further information from the field.