

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager
Freightliner Dealers– U.S. and Canada
Western Star and Sterling Dealers– U.S. and Canada
FCCC Dealers– U.S. and Canada
Thomas Built Buses Dealers– U.S. and Canada
Direct Warranty Customers – U.S. and Canada
Detroit Diesel Distributors
Export Distributors

Daimler Truck North America LLC

WARRANTY CAMPAIGNS DEPARTMENT
P.O. Box 4090 800-547-0712
Portland, Oregon 97208-4090

If you have questions about this letter, please submit your inquiry using the **WSC app on the DTNA Portal.**

REF #: ICI23-014
Effective: 04/10/2023
Release: 04/10/2023

SUBJECT: SF662 TomTom Work Instructions – Correction to Fuse Number

This letter is to inform you that step 16, page 19, of the SF662 work instructions has been updated. The referenced fuse number has been corrected from F24 to F35.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC app located on the DTNA Portal.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.