

Seal, Weather Trim Strip on Rear Doors Detaching

Topic number	LI72.12-P-076175
Version	1
Function group	72.12 - Rear door
Date	4/12/23
Validity	MODEL 206 206.0 FIN/VIN "F" up to manufacturing date: 18 January 2023 206.0 FIN/VIN "R" up to manufacturing date: 23 February 2023
Reason for change	Old part number: A2066906700 28 outer right B-pillar trim molding New part number: A2066906800 28 outer right B-pillar trim molding

Complaint

Seal, weather trim strip on rear doors detaching in upper area, see picture 1.

Attachments	
File	Description
Bild 1.jpg	Weather Trim Strip Detaching



Cause

Production deviation at supplier of weather trim strip.

Remedy

Replace weather trim strip through optimized parts.

WIS-References		
Document number	Title	Note
AR72.12-P-1713WT	Remove/install front trim strip from window frame of rear door	

Symptoms
Body > Door/Flap > Door > Door > Seal cracked/torn
Body > Door/Flap > Door > Trim > Loose

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A2066906700	27		Outer left B-pillar trim molding	1	Optionally, the part with Index 28 can also be used	X

XENTRY TIPS

A2066906800	28		Outer right B-pillar trim molding	1		X
-------------	----	--	-----------------------------------	---	--	---

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			73A0407	
			73N0407	