

WPD0 Stop delivery - Replacing engine mounts

Update 4/27/23

Please be advised that engine mounts have been allocated for certain vehicles affected by WPD0. The allocation #1 list is attached below. The allocation is only for the mounts themselves, part# V04015004AJ, Qty 2 per car. All other supporting parts can be found in the TI and can be ordered as normal via PPL.

The repair is now launched and can be completed on vehicles that receive an allocation. Further information on parts allocations / ordering will follow in the coming weeks. PLEASE REFRAIN FROM ATTEMPTS TO ORDER THE ENGINE MOUNTS (V04015004AJ).

The TI is available in PCSS and the [AfterSales Document Database](#).

WPD0 Stop delivery - Replacing engine mounts

ID Number	WPD0
Models	Panamera (971)
Model Years	2023
Number of Affected VINs	119
VIN List	Attached
Issue Description	<p>On the affected vehicles, there is a possibility that the left and right engine mounts were not manufactured according to specifications.</p> <p>This can lead to loosening of the engine mount bolts during driving.</p> <p>As a result, noise and vibrations may occur in the engine compartment area.</p> <p>Therefore, the left and right engine mounts must be replaced before the affected vehicles are delivered to the customers.</p>
What Dealers Should do	Please do not deliver the subject vehicles until the repair is completed.

The vehicles may be driven only for loading and unloading purposes in the transport chain prior to remedy.

The repair is available as of 4/27/23.

TI Number

[No. 37-23](#)

Attachments

1. [VIN_List_Report_WPD0_2023-03-13_V2.xlsx](#)
2. [WPD0 Allocation 1 list.xlsx](#)