

WPB1 Workshop campaign - Re-programming Porsche Vehicle Tracking System (PVTs) control unit

WPB1 Workshop campaign - Re-programming Porsche Vehicle Tracking System (PVTs) control unit

ID Number	WPB1
Models	Panamera (971)
Model Years	2018 - 2019
VIN List	Attached
Number of Affected VINs	16
Issue Description	<p>Due to a software error in the Porsche Vehicle Tracking System (PVTs) control unit, it is possible that the Connect services on affected vehicles cannot be commissioned successfully at locations with a poor mobile network.</p> <p>In this case, the closed-circuit current increases as a result of cyclical dial-in attempts and the vehicle electrical system battery is discharged.</p> <p>To prevent this, the Porsche Vehicle Tracking System (PVTs) control unit must be re-programmed using an updated data set.</p>
What Dealers Should do	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles. As of the time of this posting (4/28/23), the repair is immediately available.</p>
TI Number	No. 21-23

Required software

PIWIS Tester 3 test software version	41.750.060 (or higher)
--------------------------------------	------------------------

Warranty processing

Validity:

This workshop campaign will be carried out up to March 21st, 2028 and will be closed on that date.

Please note that warranty claims can only be processed before this date.

Scope 1:

Damage Code	WPB1 66 000
Repair Code	1
Labor time	28 TU

Please enter the performed campaign in the Warranty and Maintenance booklet for the vehicle.

Attachments

- [1. VIN_List_Report_WPB1_2023-04-28_V2.xlsx](#)