



# Service Bulletin

Bulletin No.: 23-NA-081

Date: May, 2023

## INFORMATION

**Subject:** Information on High Output Engine Calibration Installation Process

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2023	2023			L3B	

<b>Involved Region or Country</b>	United States, Canada
<b>Additional Options (RPOs)</b>	Equipped with RPO RWQ
<b>Condition</b>	Vehicles with an L3B engine RPO equipped with RPO RWQ High Output Engine Calibrations needs to be activated.
<b>Cause</b>	The cause of the condition may be that the engine calibration has not been activated.
<b>Correction</b>	<ol style="list-style-type: none"><li>1. Obtain the VIN of the vehicle for reprogramming</li><li>2. Call Techline Customer Support Center (TCSC) at 1-800-828-6860 English or 1-800-503-3222 French to receive RWQ ECM reconfiguration</li><li>3. Flash ECM Calibration and complete the Setup Process using Service Programming System (SPS).</li><li>4. The labor for download and the re-flash of the module is to be charged to the labor operation under Warranty Information.</li><li>5. This engine calibration is included with the vehicle transaction price and you will be provided a SPS warranty claim code upon programming completion.</li></ol>

## Service Procedure

**Important:** Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

## Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time	
*0590032	To Install High Output Calibration (RWQ)	<b>Add Time:</b>	0.3 hr

Version	1
Modified	Released April 28, 2023

