



Service Bulletin


Bulletin No.: 23-NA-086

Date: May, 2023

INFORMATION

Subject: Information on Dark Spots Noticed in Headlamp Pattern When Vehicle is Pulled Up to a Wall or Garage

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2022	2023	—	—	—	—
Chevrolet	Blazer	2023		—	—	—	—
	Traverse	2022		—	—	—	—

Involved Region or Country	United States, Canada, Mexico, Uzbekistan, Russia, Middle East, Israel, Palestine, Bolivia (West), Chile (West), Colombia (West), Ecuador (West), Peru (West), Other Africa
Condition	 <p style="text-align: right; font-size: small;">6340797</p>
Cause	This dark spot in the lighting pattern in NORMAL and part of compliance with the IIHS safety standards to minimize glare to oncoming traffic.
Correction	DO NOT replace the headlamps for this condition. This is a normal function of the lamps.

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Please communicate to the customer that the headlamp system is functioning as designed and this is a normal condition of their vehicle. Please share this information with the customer, including a copy of this message.

Version	1
Modified	Released May 03, 2023

