



Bulletin No.: PIT5856A  
Published date: 04/5/2023

# Preliminary Information

## PIT5856A Radio Screen Flicker While Up/Down Front Passenger Seat Controls Are Used

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2020 - 2023	All	All	All	All
Chevrolet	Traverse	2020 - 2023	All	All	All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Condition</b>	Some customers may comment that the radio screen will flicker or black out while the up/down front passenger seat controls are being used.
<b>Cause</b>	This condition may be caused by excessive feedback coming from the seat motor capacitor.

**Correction:**

**Do not perform any repairs at this time.**

**Please advise the customer that engineering is aware of this concern and is working on a solution.**

**When a resolution is made available a bulletin with the repair procedure will be released.**

Version History

Version	2
Modified	10/11/2021 - Created on. 04/05/2023- Updated to add model year 2023 per Bob Briedis, BQM



GENERAL MOTORS