

SERVICE BULLETIN 601 & 604 - TIGER 1200 MODELS



Notice Information

Ref	23742
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Aftersales Manager, Service Leader / Advisor
Subject:	Service/Technical

TOL NOTICE (US&CA) March 7, 2023

TOL Ref. #23742 - SVC

SERVICE BULLETIN 601 & 604 - TIGER 1200 MODELS

Dealers are requested to conduct the below service bulletins on MY23 Tiger 1200 models. Service Bulletins can be found on TriumphOnline.net (TOL) under the Service/Technical Menu item. These bulletins are also attached [601](#) - [604](#).

Reminder: use the '[VIN Enquiry](#)' function within TOL to search for any outstanding bulletins or recalls whenever a new bike arrives, or a Triumph owner visits your dealership.

SERVICE BULLETINS				
Bulletin Number	Bulletin Issue	Models Affected	VIN Range	Markets Affected
601	Detent Arm and Spring Replacement	Tiger 1200 GT, Tiger 1200 GT Pro, Tiger 1200 Rally Pro, Tiger 1200 GT Explorer, Tiger 1200 Rally Explorer	Up to BA0566	All Markets except Brazil
604	Hydraulic Clutch System Bleed	Tiger 1200 GT, Tiger 1200 GT Pro, Tiger 1200 Rally Pro, Tiger 1200 GT Explorer, Tiger 1200 Rally Explorer	Up to BJ1925	All Markets

Customer Contact Instructions

Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next visit to the dealership.

Note:

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net.

If you have any additional questions, please contact your Triumph Regional Manager or Triumph Customer Support at (888) 284-6288.