

#### 40 DTC U112100 stored in the stability control modules 00D4/00D5

40 23 56 2058460/4 May 19, 2023. Supersedes Technical Service Bulletin Group 40 number 22-42 dated June 9, 2022, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2019 – 2024		
A8 e quattro	2020 – 2021	All	Predictive Active Body Control
S8	2020 - 2024		

### Condition

REVISION HISTORY			
Revision	Date	Purpose	
4	-	Revised header (Added Model Year) Revised <i>Warranty</i> (Updated statement)	
3	06/09/2022	Revised header (Added Model Year)	
2	08/02/2022	Revised header (Added Model Year) Revised <i>Warranty</i> (Added Max TU)	

#### **Customer states:**

• No customer concerns, it is found during PDI or any other diagnostic work.

#### Workshop findings:

The following DTC is logged in the stability control module front and stability control module rear, J1152 and J1153 (address word 00D4 and/or 00D5):

• DTC U112100 (data bus missing message (passive/sporadic) with symptom code 8388618.

### **Technical Background**


Not Applicable

### **Production Solution**

Not Applicable

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

<sup>© 2023</sup> Audi of America, Inc.



#### **Service**

No repair is necessary. This DTC has no effects on the system characteristics.

# Warranty

This TSB is informational only and not applicable to any Audi warranty.

# **Additional Information**

All part and service references provided in this TSB (**2048560**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

#### © 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.