

**Volvo Car USA LLC****Technical Journal**

Technical Journal Title		Ref. No.	
Vibrations in steering wheel above 60 mph		TJ 36424.1.1	
Issuer (Dept.)		Issue Date	Status Date
Technical Service		3/20/23	4/12/23
Car Market	Partner	Function Group	
United States and Canada	3 US 7510 Volvo Car USA	4000	
Function Description		Page	
Power transmission		Page 1 of 2	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

* Vehicle Report section updated

If vibration occurs in the steering wheel mostly noticeable in speeds over 60 mph, please follow advice under "Service".

CSC Customer Symptom Codes

Code	Description
40	Steering/Vibrations in the steering wheel
V7	Complete vehicle/Vibration/When driving above 45 MPH
V2	Steering wheel/Vibration/shimmy/When driving above 45 mph
V1	Tires/Vibration/out of round

DTC Diagnostic Trouble Codes**Vehicle Type**

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536	ED	E400V6					2020-9999		-	202037-999952
539	ED	E400V6					2022-9999		-	202139-999952

SERVICE:

Please start by following TJ 32161 to first exclude that the vibrations do not emanate from the wheels or wheel alignment.

If the issue still occurs after the above has been ruled out, do not replace any parts or perform further diagnosis. Analysis is ongoing to understand this concern.

This TJ will be updated when more information becomes available.

Warranty claim info:

No warranty claim accepted for a job described in this TJ, but released as information only.

VEHICLE REPORT:

*Yes, please submit a Vehicle Report if the customer is experiencing the condition(s) described above.

*Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 4000.

*If diagnostic assistance is needed, use sub concern area "Support Needed"