

## STAR ONLINE PUBLICATION















**Case Number:** S2323000031


Release Date: April 2023

Symptom/Vehicle Issue: Buzz, Squeak, Rattle (BSR) From Under Vehicle While

Driving.

**Customer Complaint/Technician Observation:** Owner complaint BSR while driving the vehicle. The noise may change with engine RPM.

**Discussion**: Inspect the exhaust hanger screws for torque. Refer to Service Library 11 - Exhaust System / Technical Specifications.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.

Stellantis US LLC Version 4.5 07/22/2022