

REFERENCE:	TSB: 08-082-23 GROUP 08 - Electrical	Date:	April 7, 2023	REVISION:	08-062-22 REV. C
VEHICLES AFFECTED:	2022 (DS) RAM 1500 Pickup 2022 (DT) RAM 1500 Pickup 2022 (DJ) RAM 2500 Pickup 2022 (DD) RAM 3500 Cab Chassis 2022 (D2) RAM 3500 Pickup 2022 (DP) RAM 4500/5500 Cab Chassis 2022 (DF) RAM <10K Cab Chassis 2022 (RU) Chrysler Pacifica This bulletin applies to vehicles built on or before February 01, 2022 (MDH 0201XX equipped with one of the following radios: <ul style="list-style-type: none"> • Uconnect 5 W 8.4" Display (Sales Codes UFD, UPD, UBD and UED). • Uconnect 5 w 7" Display (Sales Code UBC and UEC). 			MARKET APPLICABILITY:	
				<input checked="" type="checkbox"/> NA	<input checked="" type="checkbox"/> MEA
				<input checked="" type="checkbox"/> SA	<input type="checkbox"/> IAP
				<input checked="" type="checkbox"/> EE	<input type="checkbox"/> CH
CUSTOMER SYMPTOM:	None available at this time.				
CAUSE:	Radio software				

This bulletin supersedes Technical Service Bulletin (TSB) 08-062-22 REV. C, date of issue June 24, 2022, which should be removed from your files. This is a complete revision and no asterisks have been used to highlight revisions.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 22-054, date of issue March 18, 2022. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/ Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

DISCUSSION:

The software previously released for the radio update has been removed from Uconnect download site.

POLICY:

Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.