

REFERENCE:	TSB: 23-046-23 GROUP 23 - Body	Date:	April 25, 2023	REVISION:	-
VEHICLES AFFECTED:	2022 (WS) Grand Wagoneer/Wagoneer This bulletin applies to vehicles built on or after August 01, 2022 (MDH 0801XX) and on or before November 29, 2022 (MDH 1129XX).	MARKET APPLICABILITY:			
CUSTOMER SYMPTOM:	<p>Customers may experience one or more of the following:</p> <ul style="list-style-type: none"> Fuel door won't open or is stuck closed. Tabs holding the actuator which provide the push to open function on the fuel door have broken (Fig. 1) . 				
CAUSE:	Design issue.				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-118, date of issue April 25, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.




Fig. 1
Fuel Filler Door Housings

- 1 - Broken Housing Tabs NOT Holding Actuator
- 2 - Housing Tabs Holding Actuator

REPAIR SUMMARY:

This bulletin involves replacing the fuel filler door housing.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
14-60-17-9B	Housing, Fuel Filler Door - Replace (0 - Introduction)	6 - Electrical and Body Systems	0.5 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1	68425527AD	Housing, Fuel Filler	

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the Repair Procedure. **This RSU only applies to vehicles on the RSU VIN list.**

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
Trim Stick	C-4755	Essential Tool

REPAIR PROCEDURE:

1. Replace the fuel filler door housing. Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info>23 - Body / Exterior / Housing, Fuel Fill / Removal and Installation.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.