

GROUP	NUMBER
BODY	23-BD-009H
DATE	MODEL(S)
MAY, 2023	TUCSON (NX4A) SANTA CRUZ (NXT)

SUBJECT:

FRONT DOOR PULL HANDLE PAINT PEELING

Description: This bulletin provides repair information for a non-glossy front door pull handle that exhibits paint peeling on certain 2022 – 2023MY Tucson (NX4A) and Santa Cruz (NXT) vehicles. If a vehicle exhibits this paint peeling condition, replace the front door trim panel assembly.





Applicable Vehicles (Certain):

- 2022 2023MY Tucson (NX4A) SE & SEL trims equipped with non-glossy front door pull handles and produced between 2/2/2021 – 3/29/2022 (VINs beginning with "5NM")
- 2022 2023MY Santa Cruz (NXT) SE & SEL trims equipped with non-glossy front door pull handles and produced between 5/4/2021 – 3/29/2022

Parts Information:

MODEL	PART DESCRIPTION	PART NUMBER	
		82305-CW000-MMH	
	Panel Assy-Front Door Trim, LH	82305-CW000-NNB	
	Panei Assy-Fiont Door Tilin, LH	82305-CW010-MMH	
Tugger (NIV4A)		82305-CW010-NNB	
Tucson (NX4A)		82306-CW000-MMH	
	Donal Assy Front Door Trim DU	82306-CW000-NNB	
	Panel Assy-Front Door Trim, RH	82306-CW010-MMH	
		82306-CW010-NNB	
	Danal Assy Front Door Trim I H	82305-CW000-NNB	
Conto Cruz (NVT)	Panel Assy-Front Door Trim, LH	82305-CW010-NNB	
Santa Cruz (NXT)	Danel Assy Front Door Trim DU	82306-CW000-NNB	
	Panel Assy-Front Door Trim, RH	82306-CW010-NNB	

Warranty Information:

MODEL	OP. CODE	OPERATION	OP. TIME	CAUSAL PART	NATURE CODE	CAUSE CODE
Tucson (NX4A)	30DA02R0	Door Trim Replacement LH Side Only	- 0.3M/H	82305-CW000NNB	- A42	ZZ4
Santa Cruz (NXT)	30DA02R1			82305-CW010NNB		
Tucson	30DA02R2			82305-CW000MMH		
(NX4A)	30DA02R3			82305-CW010MMH		
Tucson (NX4A)	30DA02R4	Door Trim Replacement RH Side Only		82306-CW000NNB		
Santa Cruz (NXT)	30DA02R5			82306-CW010NNB		
Tucson	30DA02R6			82306-CW000MMH		
(NX4A)	30DA02R7			82306-CW010MMH		
Tucson (NX4A)	30DA02R8	Door Trim Replacement Both Sides	0.4M/H	82305-CW000NNB		
Santa Cruz (NXT)	30DA02R9			82305-CW010NNB		
Tucson	30DA02RA			82305-CW000MMH		
(NX4A)	30DA02RB			82305-CW010MMH		


NOTE 1: Submit claim on Campaign Claim Entry screen.

NOTE 2: If a part that is not covered by this campaign needs a replacement while performing this campaign and the affected part is still under warranty, please submit a separate claim using the same repair order. If the affected part is out of warranty, submit a prior approval request for goodwill consideration prior to performing the work.

NOTE 3: The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. **Claim is subject to debit if the parts requested are not returned.**

Replacement Guide for the Front Door Trim Panel

Refer to the shop repair procedure to replace the front door trim panel:



TSB #: 23-BD-009H Page 2 of 2