

## Interior Hood Release Lever

---

Topic number	LI68.00-P-076105
Version	4
Function group	68.00 - General
Date	5/18/23
Validity	New technical condition without release handle from: - Sindelfingen factory, week of May 1, 2023 - Tuscaloosa factory, week of March 13, 2023
Reason for change	Additional Information Provided in Remedy
Reason for block	Validity Update

---

### Complaint

Technicians have reported the interior hood release lever (red) missing from vehicle.

Do not retrofit hood release lever as the part has been blocked for all EVA2 vehicles.

### Cause

Production change. Hood latch system no longer includes the interior release lever.

- The opening of the hood on all EVA2 vehicles is exclusively reserved for specialist personnel at a qualified specialist workshop.

### Remedy

No remedy required. Replacement release lever should not be ordered. See note in XPPI and Paragon. Dealers will be debited if a warranty claim for "Missing Part" is submitted.

The hood can be opened by hand using the cable. Grasp the cable with your fingers and pull on this until the hood springs.

Attachments	
File	Description
<a href="#">VID-20230418-WA0001.mp4</a>	Opening Hood Release without Lever

WIS-References		
Document number	Title	Note
AR88.40-P-1000EQS	Open hood, position vertically, close	Valid for model: 294, 295, 296, 297

# XENTRY TIPS

---

Symptoms
----------

Body > Door/Flap > Hood/flap > Engine hood > Difficult to open
--

Operation numbers/damage codes
--------------------------------

Op. no.	Operation text	Time	Damage code	Note
---------	----------------	------	-------------	------