

SSM 51660

2023 F-Super Duty - DTC U3000:41 Setting In The Audio Control Module (ACM) When A Diagnostic Self Test Is Performed

Some 2023 F-Super Duty vehicles may exhibit diagnostic trouble code (DTC) U3000:41 in the ACM when a diagnostic self-test is performed. This may be due to an ACM software error. To correct the condition, reprogram the ACM using the latest software level of the Ford Diagnosis and Repair System (FDRS) located under the SW Updates tab. For claiming, use causal part 18C869 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.