



---

**To:** General Managers, Service Managers, Service Technicians, Warranty Managers  
**From:** Mack Trucks – Service  
**Date:** May 31, 2023  
**Subject:** Service Literature Published and Released in May, 2023  
**Bulletin:** SLM23-005

---

The following summarizes the service literature that has been published and/or revised for the month.

**SERVICE NEWS**

BULLETIN #	TITLE	COMMENTS
	None Issued	

**TOOL BULLETINS**

BULLETIN #	TITLE	COMMENTS
	None Issued	

**TECHNICAL SERVICE BULLETINS**

BULLETIN #	TITLE	COMMENTS
	None Issued	

**SERVICE PROGRAMS**

BULLETIN #	TITLE	COMMENTS
S3236	Rocker Arm Adjustment	New

**RECALLS**

BULLETIN #	TITLE	COMMENTS
M0230	MY 2022 Emission Label	Revised

**CASE BASED REASONING (CBR)**

**NEW SOLUTIONS**

<b>SOLUTION #</b>	<b>TITLE</b>
CBR-2277	Battery Electric Vehicle (BEV) Sub Hardware Programming
CBR-2282	Mack GR Models - Allison Reduced Engine Load At Stop (RELS) For HydroVac Applications

**UPDATED SOLUTIONS**

<b>SOLUTION</b>	<b>TITLE</b>	<b>COMMENTS</b>
CBR-2273	Mack - Pre-Delivery Inspection (PDI) Torque Values	Improved formatting for readability.
CBR-474	Diagnostic Trouble Code (DTC) P215A-64, Fault Code SPN 84 FMI 19	Corrected mismatch in operations listed.
CBR-2255	Battery Electric Vehicle (BEV) Cab Heater Diagnostics	Updated temperature specifications.
CBR-2229	Automated Manual Transmission (AMT) Transmission Kickdown Mode	Updated the accessory kit part number.
CBR-2263	Mack Chassis - Timing Gear Plate Repair	Update to the TSB Document number
CBR-2012	Mack Chassis - SNM 20-005 - HD Disc Brake Rotor Upgrade	Added link to service news.
CBR-331	Model Year 2017 to Current - Fuel Filter Change ( Primary And Secondary ) For The EM - USA17 Emission Engines	Updated title to include model years 2017 to current.
CBR-614	Warranty Mack Chassis - eWarranty To UCHP Labor Code ( SCC Code ) Crossover, Conversion Information For Use With Campaigns ( FI, PI ) And Recalls ( EC, SC ), Location On Trucks Dealer Portal ( TDP )	Updated with updated TDP screenshots
CBR-901	Remote Control Central Door Lock, Programming; Key Fob Cannot Be Programmed Or Does Not Work After Programming - Model Year 2018 And Newer	Withdrawn for review of information.
CBR-2050	Diagnostic Trouble Code (DTC) P225C00 : NOx1 Sensor Stuck High - US17+OBD2019 And Newer Emissions	Solution withdrawn. Information superseded by CBR-2116.