Technical Service Bulletin



43 DTC U12B800 or P000000 is stored in the suspension control module

43 23 75 2058686/4 May 25, 2023. Supersedes Technical Service Bulletin Group 43 number 22-60 dated June 9, 2022 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron quattro	2019 2021 – 2023	All	Not Applicable
e-tron Sportback quattro	2020 – 2023		
e-tron S quattro	2022 - 2023		

Condition

REVISION HISTORY			
Revision	Date	Purpose	
4	-	Revised header (Added Model Year)	
3	06/09/2022	Revised header (Added Model Year)	
2	08/02/2021	Revised header (Added Model Year)	

Customer states:

• No customer concerns, it is found during PDI or any other diagnostic work.

Workshop findings:

One of the following DTCs may be stored in the suspension control module, J775 (address word 0074):

DTC U12B800 (ABS control unit implausible - passive/sporadic) with symptom code 15417397.

Or

DTC P000000 (passive/sporadic) with symptom code 15417397.

Technical Background

Not Applicable

Production Solution

Not Applicable

Page 1 of 2

© 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin



Service

If one of the DTCs described are stored in the suspension control module and no further DTCs are available in other control modules, then do not repair or replace. The DTCs listed above have no effects on the system characteristics.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All part and service references provided in this TSB (**2058686**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.