

# WPF2 Workshop campaign - Recoding the tire pressure monitor control unit

---

## WPF2 Workshop campaign - Recoding the tire pressure monitor control unit

ID number	WPF2
Models	911 Carrera GTS (992)
Model Years	2022
VIN List	Attached
Number of Affected VINs	7
Issue Description	<p>On affected vehicles, incorrect coding of the Tire Pressure Monitoring control unit means that tire combinations are stored that are not approved for the vehicles.</p> <p>For this reason, the Tire Pressure Monitoring control unit in the affected vehicles must be re-coded.</p>
What Dealers Should do	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles.</p> <p><b>As of the time of this posting (5/10/23), the repair is immediately available.</b></p>
TI Number	<a href="#">No. 55-23</a>

## Required software

PIWIS Tester 3 test software release	41.850.060 (or higher)
--------------------------------------	------------------------

## Warranty processing

### Validity:

This workshop campaign will be carried out until April 27th, 2028 and will be closed on that date.

Please note that warranty claims can only be processed up until this date.

### Scope 1:

WPF2 Workshop campaign - Recoding the tire pressure monitor control unit

Damage code	WPF2 66 000
Repair Code	1
Labor time	29 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

---

## Attachments

1. [VIN\\_List\\_Report\\_WPF2\\_2023-05-10\\_V2.xlsx](#)