

WPD4 Stop Delivery - Retrofitting camera for night vision system

Update 5/8/23

Please be advised that repairs can now begin for vehicles affected by WPD4. Parts can be ordered via PPL with no PRMS ticket needed.

The TI is available in PCSS and the [AfterSales Document Database](#).

WPD4 Stop Delivery - Retrofitting camera for night vision system

ID Number	WPD4
Models	911 (992) Taycan (Y1A / Y1B / Y1C)
Model Years	2023
Number of Affected VINs	40
VIN List	Attached
Issue Description	<p>Due to worldwide semiconductor shortages experienced by some suppliers, the affected vehicles were built without a night vision camera.</p> <p>As a result, night vision system is not available on these vehicles after leaving production.</p> <p>For this reason, the night vision camera must be retrofitted on the affected vehicles before handing the vehicles over to customers once the camera is available.</p>
What Dealers Should do	<p>Please do not deliver the subject vehicles until the repair is completed.</p> <p>The vehicles may be driven only for loading and unloading purposes in the transport chain prior to remedy.</p> <p>The repair is now available as of 5/8/2023</p>

TI Number

[No. 43-23](#)

Vehicle blocking

Vehicles must not be delivered to customers until the required remedial measure has been carried out. Therefore, please carry out following Stop Delivery, immediately.

Important Information:

- Please note that this PPN information serves as preliminary information.
- ~~At present, no statement can be made about the availability of parts. Together with our suppliers, we are working at high priority to procure the required capacities of components. As soon as these are available, we will inform you immediately. In the meantime, please refrain from requests regarding the availability of parts.~~
- ~~The Technical Information will be published at a later date.~~
- The creation of jobs as well as the invoicing the campaign is only possible with the availability of the remedial measure.
- Please also note that the use of spare parts is not allowed for the rework of the affected vehicles.

Attachments

1. [VIN_List_Report_WPD4_2023-04-05.xlsx](#)