

05/15/2023

Indian Motorcycle Misfire and Runability Diagnostics



Click here to view Team Tip I-22-09-01 (<https://www.polarisdealers.com/VirtualMaster/StopSiteFiles/TeamTips/IND/I-22-09-01.pdf>)

Indian Motorcycles has released a guide to aid in misfire diagnosis on heavyweight air and liquid-cooled motorcycles.

View Team Tip I-22-09-01 (<https://www.polarisdealers.com/VirtualMaster/StopSiteFiles/TeamTips/IND/I-22-09-01.pdf>) for additional details and diagnostics on the systems and components that may contribute to a runability or misfire concern.

Models affected by Team Tip I-22-09-01

Model Year	Models
2020-2022	Chieftain (Thunderstroke Engine)
	Roadmaster (Thunderstroke Engine)
	Springfield (Thunderstroke Engine)
	Chief (Thunderstroke Engine)
	Challenger (PowerPlus Engine)
	Pursuit (PowerPlus Engine)

Unless noted, trademarks are the property of Indian Motorcycle International, LLC
© 2023 Indian Motorcycle International, LLC

To suggest updates to the article, use the feedback form below. If you are having a technical problem or need assistance, please create the appropriate Ask Polaris Case.

Was this article helpful?

- Yes, it answers my question
- No, it is missing information or visuals
- No, the instructions are unclear
- No, What are the next steps?
- No, I am experiencing a technical error
- Other

How can we improve this article? We would love to hear your suggestions.

Tell us what you would like to see in this article

Send