

## BODY/CHASSIS – EXCESSIVE WIND NOISE

---

### Customer Voice:

- A customer may complain of a wind noise while driving in the A-pillar/ door mirror area.

### Technical Description:

- This may be caused by airflow movement over slight gaps in body trims or seals.

### Status:

- TSB JLRTB02110NAS1 is being published to address this concern.
- Should a customer express a concern, please refer to the TSB procedures for repair guidance.

22MY – Onwards Range Rover (L460)  
23MY – Onwards RR Sport (L461)

