

BODY/CHASSIS – CREAK TYPE NOISE FROM FRONT OF VEHICLE

Customer Voice:

- A customer may report a creaking type noise when steering from the front of the vehicle.

Technical Description:

- This may be caused by the steering rack contacting the front subframe at a location other than the mounting points.

Status:

- A revised front subframe machining process has been introduced to ensure proper clearance between the steering rack and subframe.
- SSM 75153 has been published to address this concern.

20MY RR Evoque
21MY Discovery Sport

