



Preliminary Information

PIT5974A Outside Mirror Puddle Lights Only Remain On For A Few Seconds

Proactive

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = A or D)	2022	All	All	All	All
Chevrolet	Silverado 1500	2023	All	All	All	All
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = H or U)	2022	All	All	All	All
GMC	Sierra 1500	2023	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment when the puddle lights, located on the bottom of the outside mirrors, turn on that they only stay on for a few seconds and then turn off.
Cause	The cause of this condition could be an issue with the Lighting Control Module calibrations.

Correction:

New updated K219 Lighting Control Module calibrations have been released to correct this condition.

Reprogram the K219 Lighting Control Module with the latest calibrations available in TLC/SPS2.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2811105	K219 Lighting Control Module Reprogramming with SPS	Use Published Time

Version History

Version	2
Modified	01/30/2023 - Created on. 05/10/2023 - Update to the Correction and Warranty sections.



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.