



Bulletin No.: PIP5916A

Published date: N/A

Preliminary Information

PIP5916A 6.6 L5P Intermittent Crank with no-start and / or Setting DTCs P062D P163A P163B P0402 P144E P2635

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500/3500	2024	All	All	6.6L L5P	All
GMC	Sierra 2500/3500	2024	All	All	6.6L L5P	All

Involved Region or Country	North America
Condition	Some 2024 Chevrolet Silverado or GMC Sierra 2500/3500 trucks with the 6.6L L5P may experience intermittent crank with no-start, and / or setting the following DTCs:P062D, P163A, P163B, P0402, P144E, or P2635
Cause	ECM Internal Software Error

Correction:

Do not replace the ECM.

Check the ECM for an update in programming.

If one is not available, please follow SI diagnostics for the DTC set.

Version History

Version	3
Modified	04/17/2023 - Created on. 05/08/2023 - Updated correction. 05/30/2023 - Updated to add DTC's P0402, P144E, and P2635.



GENERAL MOTORS