



Bulletin No.: PIP5916B  
Published date: 05/31/2023

# Preliminary Information

## PIP5916B 6.6 L5P Intermittent Crank with no-start and / or Setting DTCs P062D P163A P163B P0402 P144E P2635

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500/3500	2024	All	All	6.6L L5P	All
GMC	Sierra 2500/3500	2024	All	All	6.6L L5P	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Condition</b>	<b>Some 2024 Chevrolet Silverado or GMC Sierra 2500/3500 trucks with the 6.6L L5P may experience intermittent crank with no-start, and / or setting the following DTCs:P062D, P163A, P163B, P0402, P144E, or P2635</b>
<b>Cause</b>	<b>ECM Internal Software Error</b>

### Correction:

**Do not replace the ECM.**

**Check the ECM for an update in programming.**

**If one is not available, please follow SI diagnostics for the DTC set.**

### Version History

Version	3
Modified	04/17/2023 - Created on. 05/08/2023 - Updated correction. 05/30/2023 - Updated to add DTC's P0402, P144E, and P2635.



GENERAL MOTORS