

Subject: Engineering Information - Water Leaking Around the Interior Roof/Headliner Area

This PI has been revised to end the need for gathering information from the field. Please discard PIE0739.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade Models	2023	2023	—	—	—	—
Chevrolet	Suburban						
	Tahoe						
GMC	Yukon Models						

If you encounter a vehicle with the above condition, refer to Bulletin 23-NA-087 for further diagnosis.

Version	2
Modified	Released March 07, 2023 Revised June 07, 2023 - Ended the need for gathering further information from the field.