VOLKSWAGEN DEALER COMMUNICATION

Repair Available – Update 3708 / TCM Software Update – (NVLW)

This notice is for:	 ✓ Dealer Principal ✓ General Manager ✓ Sales Managers 	✓ ✓ ✓	Service Manager Parts Manager Service Consultant	✓ Warranty A✓ Technician	Administrator Is
Date:	June 07, 2023				
Issue:	An incorrect software version exists in the transmission control module (TCM). If the vehicle's last drive mode was Sport ("S") mode and the vehicle is restarted within 10 seconds, the vehicle will not switch back to Drive ("D") mode as it should.				
Repair:	 REPAIR AVAILABLE – June 08, 2023 Repair instructions available in ELSA/ServiceNet 				
	Update the transmission control module software.				
	• Check daily campaign open inventory report or OMD for affected vehicles in				
	 Repair every affected inventory vehicle <u>before delivery to consumers</u>. 				
	• Repair every an	ected inve	ntory venicle <u>before</u>	delivery to consume	<u>818</u> .
Affected Vehicles	Country Begi Mode	nning el Year	Ending Model Year	Vehicle	Vehicle Count
Affected Vehicles	Country Mode			Vehicle Jetta	
Affected Vehicles	Country Mode	el Year)19 pulation; son f repair to ver	Year 2019 ne vehicles may have alre	Jetta eady been repaired. Chec	Count 4 k Campaigns/Actions
Affected Vehicles	Country Mode USA 20 *Counts reflect overall possible overalle overall possible overalle overall possible overall po	el Year D19 pulation; son <u>f repair</u> to ver ation source.	Year 2019 ne vehicles may have alru ify that a VIN qualifies for	Jetta eady been repaired. Chec	Count 4 k Campaigns/Actions

-END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Volkswagen Public Relations.