

### 48 Steering wheel leather damage, all vehicles

48 23 41 2028220/10 June 20, 2023. Supersedes Technical Service Bulletin Group 48 number 21-09 dated August 25, 2021, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All Audi Models	2010 – 2024	All	Not Applicable

# Condition

REVISION HISTORY				
Revision	Date	Purpose		
10	-	Revised header (Updated Model Years)		
9	08/25/2021	Revised header (Updated Model Years)		
		Revised Technical Background (Added photos)		
8	07/12/2019	Revised header (Added Model Year)		

Steering wheel appearance damaged due to external impact (e.g., contact with fingernails, zippers, watches, rings, etc.).

## **Technical Background**

External impact (e.g., contact with fingernails, zippers, watches, rings, etc.) can cause damage to the appearance of the steering wheel (Figures 1 -6). This type of damage is not warrantable, as numerous investigations have shown that there is no fault in material or workmanship.



### Page 1 of 4

### © 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.





### Figure 1. Example of damage from external impact.

Figure 2. Example of damage from external impact.



Figure 3. Example of damage from external impact.



Figure 4. Example of damage from external impact.

## Page 2 of 4

### © 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

# **Technical Service Bulletin**





Figure 5. Example of damage from external influences.



Figure 6. Example of damage from external influences.

## **Production Solution**

Not Applicable

Page 3 of 4

### © 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



## **Service**

Not applicable.

## Warranty

This damage is due to outside influence and is not covered by any Audi Warranty.

## **Additional Information**

All parts and service references provided in this TSB (**2028220**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

#### © 2023 Audi of America, Inc.

Page 4 of 4

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.