

## **SSM 51741**

### **2022 F-Super Duty - Heated/Ventilated Seats Are Inoperative During Remote Start**

Some 2022 F-Super Duty vehicles may exhibit inoperative heated/ventilated front seats during a remote start event. This may be due to the software in the driver seat module (DSM). To correct the condition, reprogram the DSM using the latest software version of the Ford Diagnosis and Repair System (FDRS) diagnostic scan tool. For claiming, use 14C708 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.