

## Model series Z223 Maybach with code 68B Rear comfort doors - Not possible to activate the comfort doors via the front MBUX central display

---


Topic number	LI72.12-P-076545
Version	1
Function group	72.12 - Rear door
Date	6/5/23
Validity	Z223 Maybach with code 68B Comfort doors
Reason for change	

---

### Complaint

The comfort doors function is shown as "unavailable" in the MBUX display (see picture)

This means that the rear doors can only be activated via the switch in the headliner in the rear passenger compartment and not activated from the front via the MBUX display.

Attachments	
File	Description
<a href="#">Komforttür.PNG</a>	Example of function not available in rear seat display
	

### Cause

Head unit software

### Remedy

There is currently no remedy available. FUP4 head unit software will have the solution implemented. The software is planned for (Q4/23).

Note:

Do not perform any repairs at present. Replacing parts will not remedy the complaint.

# XENTRY TIPS

---

Symptoms
----------

Overall vehicle > Safety and locking system > Comfort opening/closing system > Malfunction
--

Operation numbers/damage codes
--------------------------------

Op. no.	Operation text	Time	Damage code	Note
---------	----------------	------	-------------	------