



Tips and Tricks Revision 7

Date: June 6, 2023
To: Dealer Principal, General Manager, Service Manager, North American Dealer Network
From: Richard Kenton, Technical Director
Dan Schwartz, Service Area Manager

Dear Dealers,

This bulletin is to notify you of important updates included with the recent release of Tips and Tricks Revision 7. A brief summary of each new addition is listed below, but please review the complete document hosted on DCS for further details. [Ducati - Bulletins](#)

Revision 7 New Additions		
#	Subject	Model Affected
1	Wrong preload: Range - C1020; Motor stuck – C1025	MULTISTRADA
2	Correct assembly procedure of the brake caliper mounting plate when refitting the rear wheel	MONSTER
3	Instructions to install the oil seal on the dry clutch housing	PANIGALE
4	Instructions on how to remove the timing layshaft seal	ALL MODELS

This bulletin is only applicable for Ducati Motorcycles manufactured and configured for the Ducati North American market (USA, Canada and MX).

For questions about this Service Bulletin,
please contact your Service Area Manager.