



Preliminary Information

PIT6011 After Completing The Latest Version of Recall N222382220 Some Police Options May Have Been Unintentionally Enabled or Disabled.

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Tahoe	2021	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	5W4 or 9C1
Condition	After completing the latest version of recall N222382220 some police options may have been unintentionally enabled or disabled. Example, Vehicle may have had rear park assist disabled and now it is enabled.
Cause	BCM calibrations incorrect.

Correction:

Engineering has corrected this concern and the BCM calibrations listed in TLC/SPS have been updated. Reprogram the BCM with the current calibrations listed in TLC/SPS.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*2889578	Incorrect Calibrations Reprogram BCM	0.5 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	05/04/2023 - Created.



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.