



RSB-10-23-001-1: Steering Wheel Vibration

Rivian is launching a technical service bulletin for some model year 2022 and 2023 R1T and R1S vehicles. In some situations, the driver may notice a slight vibration or oscillation of the steering wheel at 70 mph or above, causing a perceived quality issue. Steering function is not affected. Upon customer complaint of a vibrating steering wheel, Rivian will replace the steering wheel with a version that is less prone to vibration.

Document Type	Technical Service Bulletin
Date	June 14, 2023
Affected Region(s)	USA, Canada
Affected Model(s)	R1T, R1S
Model Year(s)	2022 - 2023
Approximate Build Dates	August 2021 - April 2023
 Refer to the TSB Guide Dashboard to determine if this document applies to a specific vehicle.	
Vehicle System	10 - Steering
Minimum Service Location	Mobile

Required Parts

Part Number	Quantity	Engineering Name	Service Name/Notes
One of the following:			
PT00000910-N-001		BLKEA-STEERING WHEEL - ADVENTURE; HOD	Steering Wheel; Black Mountain and Ebony Ash
PT00000910-N-002		FORBA-STEERING WHEEL - ADVENTURE; HOD	Steering Wheel; Forest Edge and Brown Ash
PT00000910-N-006		OCEEA-STEERING WHEEL - ADVENTURE; HOD	Steering Wheel; Ocean Coast and Ebony Ash

 **Attention:** The parts listed in this table are only for unique steps that are called out in this bulletin. Some sections of this bulletin might refer to Service Manual procedures which require additional parts. Always review the bulletin and all potentially related Service Manual procedures before ordering parts and beginning work.

Procedure

Replace: Steering Wheel (refer to service manual procedure 105520010).

Labor Codes

Labor Code	Description
RSB102300100	RSB-10-23-001 not applicable
RSB102300101	Replace steering wheel to reduce high speed vibration
<i>Contact ServiceDocumentFeedback@rivian.com regarding labor codes and document content.</i>	