

**UPS CAMPAIGN N764 – AIR CONDITIONING PRESSURE SENSOR CIRCUIT OVERLAY**

UPDATE PRIOR TO SALE CAMPAIGN N764 - A/C PRESSURE SENSOR CIRCUIT OVERLAY	
AFFECTED MODELS	23-24MY Range Rover Velar
VOLUME AFFECTED	US 263 CAN 21
REPAIR	A concern has been identified on certain vehicles where the Air Conditioning (A/C) system is reaching the vent off pressure due to the pressure sensor 5V power circuit missing its supply line due to a missing wire from HVAC Control Module (HVAC). Retailers are to replace the harness with a new service part.
REPAIR TIME	1.2 hrs + DIDO
CAMPAIGN LAUNCH	May 17th, 2023
Notes	Retailers should check the warranty portal to confirm affected VIN and following the bulletin service procedure must repair all affected vehicles prior to vehicle delivery.  As of June 5 <sup>th</sup> , 2023, 75 affected vehicles are in new retailer inventory.