

## JAGUAR DRIVE CONTROL FAULT WITH DIAGNOSTIC TROUBLE CODES (DTCS) STORED

### ISSUE:

Customers may report a change of Jaguar drive control to 'Comfort' mode, without driver input.

NOTE: GWM software part affected = K9C3-14F530-AA

### CAUSE:

The previous software resolved by Pathfinder is not compatible.

### ACTION:

Please follow the instructions listed on SSM 76018 for escalation to engineering for repair

### JAGUAR

- 18-20MY E-PACE



SSM76018 available on TOPIx