

BODY/CHASSIS – PANORAMIC ROOF OPENING PANEL AND/OR ROOF BLIND ONE TOUCH INOPERATIVE

23MY Range Rover, RR Sport

Customer Voice:

- A customer may complain that the roof opening panel and or roof blind one touch operation feature is inoperative after PDI.

Technical Description:

- The PDI manual did not reference to the requirement to check the one touch operation of the roof opening panel and blind, and to reset where necessary.

Status:

- The PDI manual in the TOPIx Workshop Manual has been updated (step 16 of the interior section) to include the roof one touch check.
- **SSM 76013** has been published to announce this change.
- Please do not submit a warranty claim for resetting the roof one touch operation, as the procedure is included in the PDI allowance.

