

Reference	SSM76025
Models	Defender / L663
Title	90/110/130 23MY Onwards - Loadspace Cover Damaged/Sagging - Installed In Incorrect Orientation
Category	Body
Last modified	29-Jun-2023 00:00:00
Symptom	107000 Interior Trim
Attachments	L663_Loadspace Cover_Label.JPG (L663_Loadspace Cover_Label.JPG)

Content**Issue:**

JLR is investigating reports of the Loadspace Cover being replaced due to damage/sagging.

Cause:

The loadspace cover has been installed in the incorrect orientation.

Action:

Remove and refit the loadspace cover.

When the cover is installed correctly its label (see attached image) must not be visible. The label must be on the underside of the fitted cover.

anBhdHRicnM7MjAyMy0wNy0xMFOxODowNjoyNS4yNDZaOzEzNi4yMjYyNDguODU7