

Reference	SSM76022
Models	Defender / L663 Discovery / L462 Discovery Sport / L550 New Range Rover / L460 New Range Rover Evoque / L551 New Range Rover Sport / L461 Range Rover Velar / L560
Title	TCU (Telematic Control Unit) Emergency SOS B Call Not Activated
Category	Electrical
Last modified	26-Jun-2023 00:00:00
Symptom	205000 Electrical Accessories
Content	<p><u>Issue:</u> JLR is investigating reports of vehicles being released to customers without the TCU (Telematic Control Unit) SOS Emergency Call being activated.</p> <p><u>Cause:</u> TCU activation fails to complete during the PDI routine.</p> <p><u>Action:</u> Ensure the TCU is activated during the PDI routine, and the SOS emergency call button is illuminated red, if it does not illuminate red, please repeat the TCU activation process as defined in the PDI manual until the SOS call button is illuminated red prior to customer handover.</p> <p><small>anBhdHRicm7MjAyMy0wNy0xMFQxODoxMDozNC43MjVhOzEzNi4yYU50NDguODU7</small></p>