

Subject: Engineering Information - Malfunction Indicator Lamp (MIL) Illuminated on Driver Information Center (DIC), DTCs P31A0, P31A1, P31A2, P31A3, P31A4 and/or P31A5 Set

This PI has been revised to end the need for gathering information from the field. Please discard PIE0746.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Drive Unit:
		from	to	from	to		
BrightDrop	EV600	2022	2022	—	—	—	Equipped with (RPO S8L)
GMC	HUMMER EV		2023				Equipped with (RPOs S8L, P79)
	HUMMER EV SUV	2024	2024				Equipped with (RPOs S8L, P79, P80, P8L, S80)

GM engineering has determined the root cause with the supplier for these DTCs, PIE0746 is no longer required. Findings from this EI will support part improvements. Please reference to SI for standard diagnostics for DTCs set.

Version	2
Modified	Released May 08, 2023 Revised June 28, 2023 - Ended the need for gathering further information from the field.