



# Preliminary Information

## PIC6508 B1594 SYM29, B1595 SYM29, B1597 SYM29, B1598 SYM29 Set Current With Camera Feeds Active

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Lyriq	2024	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UXP-UKL/UKR
Condition	It may be found that one or more of the following DTC's B1594 SYM29, B1595 SYM29, B1597 SYM29, and B1598 SYM29 are set as current or history with no issues with the camera feeds.
Cause	Software

### Correction:

If one or more of the DTC's listed is set as current or history and the Camera feeds are active, do not replace the K157 Video Processing Module (VPM) or attempt any repairs.

Engineering is working on a software update to correct this condition.

The vehicle can be returned to the customer, this condition will not affect the designed performance or reliability of the vehicle.

### Version History

Version	1
Modified	06/21/2023 - Created on.



GENERAL MOTORS