



Bulletin No.: PIT6037  
 Published date: 06/29/2023

## Preliminary Information

### PIT6037 Driver or Passenger Carpet Wet or Water From Console Vents

#### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2023	All	All	All	All
GMC	Canyon	2023	All	All	All	All

<b>Involved Region or Country:</b>	North America
<b>Condition:</b>	Water on the driver or passenger floor , possible water from the console vents.
<b>Cause:</b>	Pinched, restricted or misinstalled HVAC case drain tube.

If the vehicle presents with wet carpet on either or both sides of the truck or water coming from the console vents inspect the HVAC drain tube for proper installation and routing. Verify there is no debris or flashing restricting the HVAC drain .

#### Warranty Information

For vehicles under bumper to bumper warranty use the appropriate published labor operations.

#### Version History

<b>Version</b>	1
<b>Modified</b>	06/29/2023 - Created on.



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.