



Preliminary Information

PIT6038 Remote Vehicle Start Inoperative , No Response To Fob Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2023	All	All	All	All
GMC	Canyon	2023	All	All	All	All

Involved Region or Country:	North America
RPOs	-BTV / +S6P
Condition:	Remote start inoperative, usually found at PDI
Cause:	BCM has not been updated with the correct software.

Vehicles built without RPO BTV - Remote Vehicle Start but are optioned with RPO S6P - Dealer Installed Remote Vehicle Start require a BCM calibration update from TCSC to activate the function. Contact TCSC at 800-828-6860 for programming assistance.

Version History

Version	1
Modified	06/30/2023 - Created on.



GENERAL MOTORS