



Preliminary Information

PIP5934 Diagnostic Tip: Possible DTC U060F Or U1346 Set In History Or As Current

Proactive

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2022 - 2023	All	All	2.7 L3B	All
GMC	Sierra	2022 - 2023	All	All	2.7 L3B	All

Involved Region or Country:	North America
Condition:	DTC U060F or U1346 set as current or in history
Cause:	Engineering investigating root cause of condition.

Correction

You may have a vehicle come into the dealer service department with DTC U060F or U1345 set as current or in history.

If a vehicle arrives and only has these 2 DTC's please clear the codes using GDS and confirm they do not reset.

If the codes do reset perform the published SI diagnostics for the failed codes.

Engineering is currently investigating a root cause for this condition.

Do not replace the MAF sensor for this concern.

Version History

Version	1
Modified	06/30/2023 - Created on.



GENERAL MOTORS